

RENEW  $\frac{29}{32} \frac{28}{33}$  T285 R8W

FOUND - ALL FOUR ORIG  
BTS & ALL BT, EXCEPT N.E.  
BT SHOW GOOD BARK GRUBS,  
ALL CHECK FOR BEARING & DIST.  
THE N.W. BT NOW 36" FIR STUMP  
THE S.W. BT NOW 24" SING.  
THE N.E. BT NOW 40" STUMP  
(SHOWS OLD FACE I DO NOT OPEN.)  
THE S.E. BT NOW 30" FIR - DEAD.

SET BRASS CAP AT CORNER  
MND.  $\frac{529}{532} \frac{529}{533}$  T285 R8W

COUNTY SURVEYORS OFFICE 1957  
NEW BTS

14" W. FIR N 78° E 4.6' SCRIBED  
T285 R8W § 28 CS BT

12" CEDAR EAST  $390'$  SCRIBED

T285 R8W 533 CS BT

18" W. FIR § 21  $\frac{1}{2}$ ° W 19.9' SCRIBED

T285 R8W 532 CS BT

10" W. FIR N 36  $\frac{1}{2}$ ° W 44.0' SCRIBED

T285 R8W 529 CS BT

C.S. File No.  $\sqrt{49/12-11}$