

REN.

T 21 S R 7 W

$\frac{1}{4}$ S $\frac{1}{2}$ S
16 15

FD. 40" FIR N 68° E 12⁵ FT.

(ORIG. B.T. FD. IN 1959) - TREE

ALIVE & IN GOOD CONDITION.

FD. 18" FIR S 48 $\frac{1}{2}$ ° E 12⁸ FT.

MKD. IN 1959. - SCAR PITCHED OVER
& NEARLY HEALED.

THE 48" FIR TO THE S.W. (ORIG.
B.T.) IS UPROOTED & DOWN.

THE HEALOCK TO THE N.W. - MKD.
IN 1959 - IS GONE.

COULD NOT FIND BRASS CAP
SET IN 1959.

AT COR. SET NEW IRON PIPE
WITH BRASS CAP MKD. " COUNTY
SURVEYOR'S OFFICE 1963 T 21 S

R 7 W $\frac{1}{4}$ S $\frac{1}{2}$ S "

BLAZE & SCRIBE ONE NEW TREE:

13" HEALOCK S 30° W 37³ FT.

MKD. " $\frac{1}{4}$ S 16 CS BT "

COR. LIES APPROX. 100 FT. NORTH
OF RIDGE TOP.

DEC. 20, 1963

M.G.

W.S.

M.S.

J.H.

REN. #34

W. E. Coffey

+ #10

C. S. File No. 49/20-18