

RENEW NE. COR D.C. 41 T285 R5W

FOUND - BOTH B.T.S AS RENEWED 1916  
THE N.W. BT OPEN SHOWS SCRIBES MKS "C"  
THE N.E. BT SHOWS GOOD FACE I DO NOT  
OPEN B.T.S CHECKS FOR BEARING & DIST  
& BOTH ARE ALIVE & IN GOOD CONDITION  
I CAN NOT FIND 3/4" I.B.A.R. SET IN 1916  
I FIND 1/2" I.P. SET BY WOODFORD 1955  
NEARS NORTH 1/2 FROM COR  
I ALSO FIND BADLY ROTTEN BASE &  
STUMP OF ORIG. S.W. BT. NO SCRIBES MKS  
FD. CHECKS BEARING & DIST. TO COR.

SET BRASS CAP AT COR. MAD  
NE. COR D.C. 41 T285 R5W  
COUNTY SURVEYORS OFFICE 1957

No NEW B.T. SET ✓✓

DIETZGEN NO. 385-6

C. S. File No. 49/21-28