

RENEW SEC COR. $\frac{413}{910}$ T 245 R7W

FOUND - 30' x 6' x 10' SANDSTONE AT COR
28" OUT OF GROUND. CHECKS RECORD FOR
SIDE BUT I CANNOT FIND ANY NOTES
THAT I AM CERTAIN OF

ORIG. 8" NOW 12" ROTTED STUMP
SET 60.7' NB SCREWBING FD.

ORIG. 14' NOW 25" FIR DOWN, I OPEN
FO SER. BE MKS. 560' W 142'

ORIG. 40' NOW 50" FIR SHOWS GOOD
SCAR I DO NOT OPEN N 30° W 343'

ORIG. 16" NOW 26" FIR N 55° E 145'
SHOWS GOOD SCAR I DO NOT OPEN.

NOTE - ALL CHECK RECORD
DIST # BEARING.

SET BRASS CAP AT COR. MKD.
39133 T 245 R 7W COUNTY SURVEYORS
59 310 OFFICE. 1957

NEW BTS
12" R. FIR BEARS 530' W 28° E 282'
59 T 245 R 7W 53 BT

4' HEMLOCK BEARS 375' E 20° E 282'
310 25 BT

THE ORIG N 1/2 E N.W. BTS ALIVE &
IN GOOD CONDITION.

NOV 29-57
J. BYRON
M. GARDNER
S. BLOW

MAR 20 1958

C. S. File No. 49/410

DIETZGEN NO. 3888-6