

RENEW $\frac{1}{4}$ COR 29/28 T245 R7W

FOUND - $\frac{1}{4}$ " I.P. AT CORNER. ~~IN~~ BOTH
BTS. RECORDED BY EPP. 1928
18" NOW 28" FIR STUMP N 17° W 190'
FOUND GOOD SCRIBING. SE BT
NOW DOWN.

SET BRASS CAP ALONGSIDE COR.
PIPE MARKED $\frac{1}{4}$ S 29 | S28 T245 R7W

COUNTY SURVEYORS OFFICE 1960
NOTE - COR UNDER 60" FIR TREE (DOWN)

NEW BTS.
20" P. FIR BEARS N 57° W 110'
SCRIBED $\frac{1}{4}$ S 29 CS BT

20" R. FIR BEARS N 58° E 78'
SCRIBED $\frac{1}{4}$ S 28 CS BT

RENEW S29 | S28 T245 R7W
S32 | S33

FOUND - ALL THREE BTS. AS
RECORDED BY EPP - 1928. EXCEPT
WE FIND NE BT SHOULD BE
N 59° E (RECORD N 62° E). BTS.
STILL GOOD SCARS IF DO NOT
OVER.

SET BRASS CAP AT CORNER

MKD. S29 | S28 T245 R7W
S32 | S33

COUNTY SURVEYORS OFFICE 1960

BTS. ARE ALL IN GOOD CONDITION
NO NEW BTS. SCRIBED.

NOTE - PIPE SET BY EPP AT COR.
NOT FOUND

RECEIVED

AUG 31 1960 AR 2010 AUG. 30-60

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

J. B.
A. G.
C. P.

C. S. File No. 49/41-33

DIETZEN NO. 385-6