

RENEW CC 16 T245 RTW

FOUND - ORIG 50" FIR NOW 55"  
PREVIOUSLY OPENED SHOWS GOOD  
SCRIBING "245 W" ORIG. 40" NOW 48"  
FIR S 57° E 23.1' ORIG 28" NOW 48" FIR  
S 64° W 22.8'

SET BRASS CAP AT COR. MKD  
COUNTY SURVEYORS OFFICE 1960

CC 16 T245 RTW

NEW BTS

12" R FIR BEARS S 82° E 19.7'  
SCRIBED S 7 T245 RTW CS BT

6" R FIR BEARS N 70° E 28.9'  
SCRIBED S 6 T245 RTW CS BT

RENEW T235  
REW 1 6 RTW

T245

FOUND - ORIG. 36" NOW 48" FIR N 38° W 56'  
OLD FACE DESTROYED BY FIRE. ORIG  
36" NOW 42" FIR S 57° E 54.8' OLD FACE  
DESTROYED BY FIRE. ORIG. 40" NOW 65" FIR  
S 10° W (RECORD 557A) 29.2' NOW  
STUMP SHOWS ROTTED FACE.

SET BRASS CAP AT CORNER MKD  
COUNTY SURVEYORS OFFICE 1960

CC T235

S 10° W T245

REW RTW

~~RECORDED~~

NEW BTS

4" R FIR BEARS S 13° W 15.4'  
SCRIBED S 1 CS BT

RECORDED NOW 42" R FIR. S 57° E 54.8'  
CC S 6 T245 RTW CS BT

DIETZEN NO. 395.6