

Renewal # 36

19 | 20  
30 | 29

T245 R2W1

Found-

13' W/Oak NW 25' N86E 68°  
Partial scribe marks visible (down)

15" D Fir NOW DOWN N39W 100°

30' D Fir NOW STUMP S86E 28°  
Scribe visible "BT"

Also steel AXK at SW cor

Renewal

New Bearing Trees

19" D. Fir N44W 91°  
Scribe BT T245 R2W S19 CS BT

15" D. Fir N15E 87°  
Scribe BT T245 R2W S20 CS BT

Note NO OTHER TREES available

12-9-70

~~12-9-70~~

D. W. J. W. 31

#115

C. S. File No.

49/41-63

DIETZEN NO. 385-6