

Renewal # 15

3 12
10/11

T295 R2W

Found

26" D Fir Now 29" S55E 27°
Scribe visible "3"

22" D Fir Now 26" S12W (Old S1195E) S5°
Scribe visible "3"

Also 1" steel shaft of sec cor.

DIETZGEN NO. 388-6

Renewal

New Bearing Trees

8" D Fir N 29 W 70°
Scribed T295 R2W S3 CS BT

11" D Fir N 73 E 35°
Scribed T295 R2W S2 CS BT

Redwood & Rescribed

26" D Fir S12W 55°
Scribed T295 R2W S10 CS BT

Note: This cor lies 8' East
of N-S Fence line

12-10-70

O. V. K.
F. W. (S)

~~J. M. K.~~
~~F. W. (S)~~

#114

C. S. File No. 49/41-67