

RENEW NORTH $\frac{1}{4}$ 51 T 295 R 3 W

FOUND - BOTH ORIG BTR ORIG.
12" NOW 18" FIR S 52° E 6.6' T OPEN
5" FIND GOOD SCRIBING $\frac{1}{4}$ 51 ORIG
12" NOW 16" FIR N 32° W 6.6' CENTER
ROTTED NO SCRIBING FD.
COR. STONE NOT FD.

SET BRASS CAP AT COR. MKD.
COUNTY SURVEYORS OFFICE 1960.

T 295

N $\frac{1}{4}$ 51 T 295 R 3 W

NEW BTR

24" R CEDAR BEARS S 43° E 36.5'
SCRIBED N $\frac{1}{4}$ 51 CS BT

5" X FIR BEARS S 57° W 59'
SCRIBED N $\frac{1}{4}$ 51 CS BT

FEB 1 - 1960
J. B.
M. G.
C. D.

RENEW 35 36 T 285 R 3 W

FOUND - ORIG. 8" NOW 20" LAUREL
N 26° W 25.1' BEARS GOOD SCRIBING
ON OLD FACE ORIG. N E RT FACE DOWN
IN POOL. NOTE - COR. IN POOL I DO NOT
SET BRASS CAP. NORTH $\frac{1}{4}$ 51 T 285
BEARS S 80° E 58.1'

NEW BTR

12" R FIR N 33° W 21.6'
SCRIBED CC S 35° T 285 R 3 W CS BT

7" R FIR BEARS N 20° E 38.2'
SCRIBED CC 36 T 285 R 3 W CS BT

DIETZEN NO. 385-6

C. S. File No. 79/47-10