

RENEW $\frac{1}{4}$ COR $3\frac{1}{2}$ T 305 R3W

FOUND - ORIG 30" NOW CO" FIR
STUMP S 22 $\frac{1}{4}$ E 203' I OPEN &
FIND GOOD SCRIBING "4" ORIG
6" NOW 12" CHINOQUIN 518' W 4.3'

SET BRASS CAP AT CORNER
MND COUNTY SURVEYORS OFFICE
1960 $\frac{1}{4}$ S 3152 T 305 R3W

NEW BTS.
10" R. FIR BEARS N 41° E 209'
SCRIBED $\frac{1}{4}$ S 2 C S BT

RESCRIBE 12" CHINOQUIN 518' W
4.3' $\frac{1}{4}$ S 3 C S BT

VAR 205° JULY 22-60
J.B. M.G. CP.

RENEW $\frac{1}{2}$ COR S 35 T 295 R3W

FOUND - ORIG 6" NOW DOWN 10"
LAUREL N 30° E 332' I OPEN & FIND
GOOD SCRIBE MARKS $\frac{1}{4}$ 8" THIS BT
WAS FOUND DOWN HILL ABOUT 30'.
WE FOUND MATCHED STUMP SECTION
WHICH FIXED LOCATION OF BT. ORIG
SE BT NOT FOUND.

SET BRASS CAP AT CORNER &
ALONGSIDE 10" R. FIR (EAST SIDE)
MARKED CAP COUNTY SURVEYORS
OFFICE 1960 SOUTH $\frac{1}{4}$ S 35 T
295 R3W.

NEW BTS.
10" R. FIR BEARS N 44 $\frac{1}{2}$ ° E 152'
SCRIBED $\frac{1}{4}$ S 35 C S BT

11" R. FIR BEARS N 65° W 5.8'
SCRIBED $\frac{1}{4}$ S 35 C S BT

NOTE - 57' RED SET BY SHANER
FOR NORTH $\frac{1}{4}$ S 2 T 305 R3W

BEARS N 87° W 76.5' ✓
SEE M 17-51 ✓ ✓ 49/4716

DIETZGEN NO. 385-6