

DIETZGEN NO. 388-B

RENEW  $\frac{1}{4}$  COR. T 265 R 3W

CORNER RENEWED BY REBUN OF TIE  
SHOWN ON PLAN CS FILE # 47/112  
 $\frac{1}{4}$  COR. AT CHORD OF NEW NORTH W. HGY. ALL  
PTS. NOW GONE, TAKEN OUT DURING CONST. OF  
ROAD.

SET BRASS CAP AT CORNER MKD.  $\frac{1}{4}$  S  
T 265 R 3W COUNTY SURVEYORS 392  
OFFICE 1957.

NEW PTS.  
12' R. FIR BEARS S 30K° E 12.31'  
SCRIBED  $\frac{1}{4}$  S 12' CORNER

36' CEDAR BEARS N 46° E 30.5'  
SCRIBED  $\frac{1}{4}$  S 1' CS CORNER

49357

DR. 18-57  
T 265 R 3W  
M 265 R 3W  
S 265 R 3W

VAD 20K

NORTH UNDEVELOPED  
265  
392