

RENEW MC

T 26 S
R 3 W
S 9

LT BANK

FOUND - BRASS CAP AT COR. MARKED AS RECORDED. ALSO BOTH B.T.S. THE BRASS CAP IS NEAR WATER SURFACE AND WOULD PROBABLY BE WASHED OUT BY NEXT HIGH WATER.

I MOVE CAP 30' EAST AND ADD THIS TO CAP " MOVED 30' EAST CS 1960"

I RESCRIBE BOTH ORIG. B.T.S.

36" R. FIR BEAMS N 40° W 9.1' SCRIBED S 9 WC MC CS BT

10" ASH BEAMS S 85° W 8.4' SCRIBED S 16 WC MC CS BT.

YAR - 20 1/2°

MARCH 18 - 60
J. P.
C. P.

ORIGINALLY
THIS CORNER SET IN 1924.

DIETZEN NO. 3855-6

*

✓

C. S. File No. 49/70⁸⁰