

RENEW $\frac{3}{10}$

T 23 S R 8 W

FOUND - 3 ORIG. BTS. & OLD
 MADE STUNTO THAT CHECKS
 BEARING & DIST FOR SETTING
 ORIG 12" W. FIR NOW 32" SHOWS
 OLD FACE NOW ROTTED N 32° E 49.5'
 ORIG 40" NOW 52" FIR SETTING 44.9'
 SHOWS GOOD SCURS I DO NOT OPEN
 ORIG. 104" NOW 28" R. FIR N 82° W 19.5'
 SHOWS SCURS I DO NOT OPEN. ALSO
 FIND TRACK SET FOR CLOSING COR
 2 CHECKS GOOD FOR BEARING
 I I MAKE DIST ABOUT 4' LESS
 THAN RECORD.

SET BRASS CAP AT CORNER MKD,
 COUNTY SURVEYORS OFFICE 1959.

3/10/59 T 23 S R 8 W

DIETZGEN NO. 38545

NEW BTS
 10" R. FIR BEARS N 77° W 36.3'
 SCRIBED S 3 T 23 S R 8 W C 2 BT

8" R. FIR BEARS S 72° W 42.6'
 SCRIBED S 10 T 23 S R 8 W C 2 BT

JUNE 30 - 59
 H. R.
 M. G.
 W. B.
 C. R.

V 1220 5°