

29128
RENEW SEC. COR. 32 33 T 22 S R 5 W

FOUND - ORIG 18" NOW 36" ROTTED
STONE NOISE 416' THIS BT OPENED
YEARS AGO. NOW HAS ONLY SECTION
OF ORIG. FACE IN PLACE, WITH GOOD
SERIBS "528 27". I ALSO FIND
30" FIR THAT CHECKS RECORD DIST
BEARING FOR ORIG. 7" FIR 566' W
47' I DO NOT OPEN AT CORNER.
I FIND MOUND OF STONE # 12" X
12" X 12" STON WITH CHILLED #

SET BRASS CAP AT COR. # ALONG
SIDE MOUND OF STONE, MKD.

~~529 528~~
532 533 T 22 S R 5 W COUNTY
SURVEYORS OFFICE, 1958.

NEW BTS.

24" R. FIR BEARS 586° W 188'
SCRIBED 533 T 22 S R 5 W C S BT.

7" R. FIR BEARS N 32 5° E 143'
SCRIBED 538 C S BT.

8" WHITE FIR BEARS N 40 5° W 515'
SCRIBED 529 T 22 S R 5

33" R. FIR BEARS SOUTH 264'
SCRIBED 532 T 22 S R 5 W C S BT.

VAR. 20 ± °

JAN 21 - 58
J. B.
M. G.
J. B.

DIETZEN NO. 385-B