

RENEW SEC. COR. $\frac{5}{8}$ T 22 S
R 5 W

FOUND - ORIG 2 1/2" NOV 30" B. OAK
3 1/2" S 75° W 139.4' THIS BT WAS
FOUND & APPARENTLY RE-SCRIBED BY
THEM IN 1899. SEE BOOK # 19 JOB 17
TO OPEN THIS BT & FIND THE 1/2" BT 2"
UNDER SURFACE. I CUT OUT THIS BT
AND FIND THE ORIG. BT SCRIBING ABOUT
5" UNDER SURFACE. ALL OTHER ORIG.
BTS GONE. I A 60 FIND 3/4" I.R. & OLD
SCRIBED 4" X 6" POST AT THE 1/2" COR.
FROM WHICH NOW 28" R. FIR BEARS S 75° W
132' TO OPEN & FIND GOOD SCRIBING
3/4" I.R. BEARS S 20° E 172'

I USE RECORD DIST & BEARING FROM
ORIG. SW BT TO ESTABLISH THIS SEC
COR. AS THE EVIDENCE AT THIS TIME
INDICATES THE 1/2" WAS IN ERROR
IN THE LOCATION OF THE COR.

SET BRASS CAP AT COR. NAD T 22 S
R 5 W 5 1/2 S COUNTY SURVEYORS OFFICE
37158 1958.

NEW B.T.S.

10" R. FIR BEARS S 77° W 134.8' SCRIBED
T 22 S R 5 W 5 1/2 S BT.

14" R. FIR BEARS N 52° W 118.8' - -
T 22 S R 5 W 5 1/2 S BT.

8" R. FIR BEARS N 30° E 139.4' SCRIBED
T 22 S R 5 W 5 1/2 S BT.

10" B. OAK BEARS S 4 1/2° E 168.2' - -
T 22 S R 5 W 5 1/2 S BT.

VAD 20 1/2"

JAN 7 - 58
J. B.
M. C.
S. B.

C.S. File No. 49/59.8