

REN. T 23 S R 10 W $\frac{1}{4}$ S $\frac{26}{35}$

FD. DOUG. FIR (NOW 42" DIAM.)

N 65° E 44⁰ FT. - SCRIBING VISIBLE, $\frac{1}{4}$ S 20

FD. DOUG. FIR (NOW 32" DIAM.)

N 39° E 39⁰ FT. - FACE OPEN, BUT
PITCHED OVER.

AT COR. SET IRON PIPE WITH
BRASS CAP MKD. " COUNTY SURVEYOR'S
OFFICE 1964 T 23 S R 10 W $\frac{1}{4}$ S $\frac{26}{35}$ "

BLAZE & SCRIBE ONE NEW TREE:

6" HEMLOCK S 26° W 24² FT.

MKD. " $\frac{1}{4}$ S 35 C S BT "

NOTE - FD. OLD, ROTTED CEDAR

STUMP SCRIBED " $\frac{1}{4}$ S " ON E. FACE

S 33¹/₂° W 28² FT. - WHICH I BELIEVE TO
BE AN ORIG. B.T. - DOES NOT FACE
RIGHT FOR CALL IN GOV'T NOTES FOR
B.T. - NO OTHER OLD TREE FD. TO
MATCH IT, EVEN IF BEARING GIVEN
IS IN WRONG QUADRANT.

COR., AS RENEWED BY ME, IS
RERENEWAL OF COR. AS SET BY
OREGON STATE BOARD OF FORESTRY
ONLY. - NOT RENEWAL OF ORIG. COR.

MAY 28, 1964

+ X *M. G. W. S.*
REN. #20

M. G.
W. S.
M. D. 4/16/65
M. S.