


RENEWAL  $\frac{9}{16}$  T285 R5W

FOUND - DRILL STEEL AT COR.  
 NOW 2" W. OAK BEARS N77°E NOT  
 N70°E 29.7' SHOWS GOOD SCARS.  
 ORIG. W. OAK BEARS S56°E  
 NOT 5605°E 37.0'. D.I.A. OF W. OAK  
 BAW 29".

NOTE - FENCE COR. THUS



Nov. 2 - 1961

U.S.

D.M.

VAR 20 1/2° U.P.

+ \* / O

RENEWAL  $\frac{9}{16}$  T285 R5W

FOUND - 12" NOW 16" B. OAK N69 1/2° W  
 33.7' SHOWS GOOD SCARS WE DO NOT  
 OPEN WE ALSO FIND ORIG. SW &  
 SE B.TS. THE SW BT NOW STUMP  
 SHOWS GOOD REVERSE SCRIBING THE  
 SE BT CENTER KOTTED SHOWS  
 REVERSE SCRIBING. WE FIND OLD  
 OAK SCRIBED 8' X 4' ON GROUND AT  
 CORNER.

SET BRASS CAP AT COR. NIND.  
 COUNTY SURVEYORS OFFICE 1961.

S4510  
 S76515 T285 R5W

NEW B.TS.

19" W. OAK BEARS S 80 1/2° E 31.7'  
 SCRIBED S 15 T 285 R5W CORN

12" W. OAK BEARS N 49 1/2° W 28.5'  
 SCRIBED S 10 R 5 R 5

21" B. OAK BEARS S 77 1/2° W 44.0'  
 SCRIBED S 16 T 285 R5W CORN

FENCE COR THUS



566°E

+ \* / O - 31°

U.S. No. 19/64-24