

REVIEW ¹⁴¹³ T 285 R 5 W

FOUND - ORIG. 48" NEW 48" FIR
IMAG N 19° E 310' SHOWS GOOD
BANK SCARPING 1 BT. WE HAD
FIND REMAINS OF S W & N W CORNERS
SEE BT NOW DOWN. WE FIND SQUARE
TAKE DOWN AT COR.

SENT BRASS CAP AT COR. MIKO
COUNTY SURVEYORS OFFICE 1961
SM 153 T 285 R 5 W
523522

NEW BT'S.

9" CEDAR BEARS S 89° E 17.6'
SCRIBED S 24 CS BT

26" R. FIR BEARS N 88° E 55.6'
SCRIBED S 13 T 285 R 5 W CS BT

14" R. FIR BEARS N 62° W 36.7'
SCRIBED S 14 T 285 R 5 W CS BT

8" CEDAR BEARS S 61° W 28.3'
SCRIBED S 23 CS BT

DIETZEN NO. 385-6

FILED
RECEIVED

NOV 20 1961

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

NOV 25 - 1961

C.S. FILE NO. 49/64-11