

RENEW 26125 T 2 2 2 R 5 W
35 36

FOUND 1" 1/2" I.P. AT COR. AND
ALL MARKINGS BT'S ALSO ORIG.
SW & NE BT'S SHOW SCRIBING
DOWN 20' B.O. S 23° W 55' 8"
SHOWS SCRIBING ON PARTLY
CLOSED FACE

DESCRIBE ORIG. 24' NOW 40'
LAUREL S 20° E 80' S 36-285
R SW COR BT

16" CEDAR BEARS N 68° W 108'
SCRIBED S 26 T 285 R SW COR BT

12" R. F. I. BEARS N 36 1/2° E 49.3'
SCRIBED S 25 T 285 R SW COR BT

NOTE - 1" 1/2" I.P. AT COR. IS OK,
MARKINGS N W BT IS DOWN.
NE & SE BT'S NOW SNAGS

NOV 30 - 1961
H. B.
H. P.

DIETZEN NO. 3886

FILED
RECEIVED

NOV 30 1961

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

C. S. File No. 49/64