

RENEW. $\frac{1}{4}$ COR 15/14 T295 R5W

FOUND - $\frac{7}{8}$ " I.R. AT COR. $\frac{1}{4}$

BOTH BTS AS RECORDED BY EVANS

EXCEPT NW BT NOW STUMP

NOTE - $\frac{1}{4}$ COR IS 8' WEST OF
N.S FENCE

NEW BT.

44 LAUREL BEARS N 17° W 50' 2"
SCRIBED $\frac{1}{4}$ S 15' S BT

VAR 205'

MAY 6 - 1962

J. H. H. P.

D. H. H. P.

~~RENEW~~ $\frac{1}{4}$ COR. $\frac{8}{17}$ T295 R5W

FOUND -

ORIG. 24" NW 36" LAUREL
335° E 39.6' PREVIOUSLY OPENED
SHOWS GOOD SCRIBING $\frac{1}{4}$ S BT

WE ALSO FIND BOTH BTS,
(NOW STUMPS) THE NW BT SHOWS
SCRIBING AS RECORDED BY
CANAINS COR. BEARS 140° E 125'
WE DO NOT FIND ORIG. NE BT

IF USE ORIG. SE BT TO FIX
POSITION OF $\frac{1}{4}$ COR. I BELIEVE
THAT CAN EITHER WAS IN
OR DID NOT FIND ORIG. SE BT.
MY LOCATION OF $\frac{1}{4}$ COR. IS
LOCATION OF OLD $\frac{1}{4}$ COR.

SET BRASS CAP AT COR. MKD
 $\frac{1}{4}$ S $\frac{8}{17}$ T295 R5W COUNTY

SURVEYED BY J. H. H. P. & D. H. H. P.
NEW BT.
R. H. H. P. BEARS 140° E 125' COR.
SCRIBED $\frac{1}{4}$ S 15' S BT (SCRIBED HIGH)

NOTE - COR IS ON STEEP NORTH
SLOPE TO NORTH OF E.W. RIDGE

DIETZGEN NO. 385-B

3/19/62

3/19/62
C.S. FIG. No.