

RENEW $\frac{1}{4}$ COR 9 T 2 S R 7 W

FOUND - BOTH ORIG B.T.S. & NEW 14" W. FIR SCRIBED BY KERR 1953 -
 I DO NOT FIND HIS 3 V. BT
 NEW 30" SET CORNER. I FIND 30" STUMP SCRIBED "BT". THIS IS BT USED BY KERR TO SET CORNER. I ALSO FIND NEW 25" W. FIR SNAG PREVIOUSLY OPENED SHOWS GOOD SCRIBING "BT". THIS IS ALSO AN ORIG. BT. WAS 25" W 25" S. I USE THIS BT TO SET COR WHICH CHECKS RECORD DIST TO STUMP BUT I FIND BRASSING SHOULD BE 325° W RECORD SIZE. ALSO B.T.S. POINT TO THIS COR RATHER THAN TO KERR'S COR.

KERR'S COR BEARS N 85° W 145'

SET BRASS CAD AT CORNER MND COUNTY SURVEYORS OFFICE, 1959

$\frac{1}{4}$ S 9 T 2 S R 7 W
S 16

NEW B.T.S.

12" CHINDUIN BEARS N 43° W 65.8' SCRIBED $\frac{1}{4}$ S 9 CS BT.

12" W. FIR BEARS S 83° E 44.7' SCRIBED $\frac{1}{4}$ S 16 CS BT.

NOTE - COR IS IN SOUTH EDGE OF LOG RD.

NOTE - I DESTROY SCRIBING ON KERR'S B.T.S.

APRIL 14 - 59
J. BYRON
M. GODFREY
S. BILLOW

DIETZGEN NO. 385-6