

RENEW MC

NORTH LINE  
D.L.C. 38

T 253 R7W

25' 30" E  
1" PIPE

R6W

FIND - B.B.I. 19" B. OAK NEW 22"

SHOWS GOOD SCARS I DO NOT OPEN

NOTE - COR FALLS ON STEEP BANK SLOPE

I DO NOT FIND 1" PIPE SET BY B.B.I.

GET BRASS CAP IN FENCE LINE E.  
44' WEST OF CORNER. MARK BRASS  
CAP W.C.

44' EAST TO MC - D.L.C. 38

COUNTY SURVEYORS OFFICE 988 525 520

T 253

R7W

R6W

NEW BT.

RESCRIBE 22" B. OAK N15°E 139'

W.C. MC 530 525 CS B -

DIETZEN NO. 388-6

FILED  
RECEIVED

AUG 22 1958

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

C.S. File No.

49/76-9