

RENEW 1/2 CORNER = T255 12 74V

27
486

FOUND - OR 16" CEDAR NOW 32"
STUMP 339' W/1/4 I OPEN OLD SCAR
NEAR BASE 3' FROM GOOD SCRIBING "B"
I ALSO FND 25' W. FR SNAG THAT HAS
BEEN BARK SCRIBED HAS BT BEARS
N39° E 48.6' RECORD IS N12° W 50.8'
I DO NOT BELIEVE THIS IS THE ORIG. BT.
SCRIBING DOES NOT SEEM TO BE OLD ENOUGH
THE ORIG. N. W. V. BT WOULD BE UNDER
LOG ROAD FILL.

I USE THE ORIG. SW BT TO FIX
POSITION OF 1/4 COR.

SET BRASS CAP AT CORNER 1/4 COR.
1/4 S 31 COUNTY SURVEYOR'S OFFICE 1957

NEW B.T.S.
7" R. BT BEARS 10.2'
SCRIBED 11.5' BT
13' CEDAR BEARS N7° W 64.4'
SCRIBED 11.5' BT

THIS CORNER MAY BE MOVED
TO AGREE WITH US GLO DONE
DO NOT USE - 10-7-58 - PUT IN BOOK
5-59

DIETZEN NO. 385-6

FILED
RECEIVED

MAY 29 1958

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

C. S. File No. 49/76.12