

RENEW  $\frac{1}{4}$  COR. 22/23 T255 R3W

FOUND - BRASS CAP BENT & PARTLY

OUT OF GROUND. I ALSO FIND BURNED

S86°W 271'

48" FIR SNAG THAT SHOWS GOOD SCRIBING.

BT 5". I FIND NO TRACE OF SE BT.

IT WOULD BE IN LOGGING ROAD. I FIND

STEEL FENCE POST AT CORNER.

I STRAIGHTEN & RESET BRASS CAP

AT CORNER.

NEW BTS.

18" HEMLOCK BEARS S 82° E 49.0'

SCRIBED  $\frac{1}{4}$  S 23 CS BT

48" R. FIR BEARS N 24° W 49.0'

SCRIBED  $\frac{1}{4}$  S 22 CS BT

VAR. 2040 AUG 15-58

J. B.

M. G.

S. B.

✓  
CS 49/78-3