

RENEW $\frac{1}{4}$ COR. 819 T27S R6W


FOUND - BRASS 13" NOW 40" B.O.
57#⁰ W 94.4' SHOWS GOOD SCAR
WE DO NOT OPEN ORIG. 14" NOW
20" B.O. 34# E 179.3' WE OPEN #
FIND GOOD SCRIBING "B".

SET BRASS CAP AT COR. MKD.
COUNTY SURVEYORS OFFICE 1961
 $\frac{1}{4}$ 3819 T27S R6W.

NEW BTS.

10" W. OAK BEARS N $14\frac{1}{2}^{\circ}$ W 29.3'
SCRIBED $\frac{1}{4}$ S 1 C S BT.

10" W. OAK BEARS N 18° E 34.8'
SCRIBED $\frac{1}{4}$ S 9 C S BT.



JAN 9 - 1961
J. H.
M. S.
C. P.

RENEW $\frac{1}{4}$ COR. 30129 T27S R6W

FOUND - BRASS CAP AT COR. $\$$ AT FENCE
COR. $\$$ BOTH ORIG. BTS. SHOWS SCARS
WE DO NOT OPEN.

NEW BTS.

14" B. OAK BEARS N 77° E 5.6'
SCRIBED $\frac{1}{4}$ S 29 C S BT

7" W. OAK BEARS S 64° W 21.2'
SCRIBED $\frac{1}{4}$ S 30 C S BT

FILED

RECEIVED

Refer to Renewed Corner by Surveying

JAN 11 1961

C.S. 43/99

COUNTY SURVEYOR

* DOUGLAS COUNTY, ORE.

C.S. File No. 49/79⁵

DIETZGEN NO. 385-6