

T 27 S R 7 W

COR. OF SECS. 32 & 33

FD. IRON PIPE WITH BRASS  
CAP MKD.

T 27 S R 7 W  
S 32 | S 33 AP 5

FD. 16" FIR STUMP N 66° E 1924  
18 5/8 FT. SHOWS GOOD SCAR.

FD 36" LAUREL N 65° W 26 1/4 FT.  
ALIVE & IN GOOD CONDITION. DID  
NOT OPEN.

BLAZE & SCRIBE ONE NEW TREE:

24" LAUREL N 39° E 16 1/2 FT. MKD.  
"T 27 S R 7 W S 33 CS BT"

COR. LIES ABOUT 10 FT. WEST OF  
FENCE COR. (NEW FENCE). FENCE  
RUNS EAST & NORTH.

POINT ESTABLISHED BY FORD FOR  
COR. SECS 32 & 33. RE-ESTABLISHED AS  
ANGLE PT.

FD. IRON PIPE WITH BRASS CAP  
MKD. "AP 1924"

FD. 14" FIR STUMP S 41° E 23 1/4 FT.  
SHOWS GOOD SCAR.

FD. 8" FIR STUMP S 00° W 7 3/8 FT.  
UPROOTED & LYING FACE DOWN.

DID NOT LOOK FOR 2 ORIG. TREES.

BLAZE & SCRIBE 2 NEW TREES:

22" LAUREL N 46 3/4° E 28 5/8 FT.  
MKD. "AP CS BT"

12" CEDAR N 54° W 66 1/4 FT. MKD.

"AP CS BT"

FEB. 20, 1961

2/1961

C. S. F.

J. B. M. G. C. P.

Milo E. Jeffrey

49/79-31