

T 28 S R 7 W

N.W. COR. SEC. 4 ONLY

AT COR. FD. IRON PIPE WITH  
BRASS CAP MKD.

FD. 12" LAUREL S 72° E 29 <sup>7</sup>/<sub>8</sub> FT. S 4  
T 28 S  
R 7 W  
S 4  
SHOWS SCAR. TREE IN GOOD CONDITION  
OAK B.T. CALLED FOR-GONE 1924  
NO TRACE.

THE LAUREL S 30° W 31 FT. STILL  
STANDING, BUT ROTTED OUT INSIDE  
BLAZE & SCRIBE NEW TREE:  
10" FIR N 55° E 6 <sup>3</sup>/<sub>8</sub> FT. (N.W. S 4 CSBT)

T 27 & 28 S R 7 W

HATHORN'S POINT FOR STANDARD  
COR. SECS. 4 & 5 - RENEWED AS A.P.  
FD IRON PIPE WITH BRASS CAP.  
MKD. "AP 6 1924"

FD. 14" FIR STUMP N 50° E 19 <sup>4</sup>/<sub>8</sub> FT.  
FD. 14" FIR STUMP N 60° W 4 <sup>6</sup>/<sub>8</sub> FT.  
BOTH STUMPS SHOW GOOD SCAR.  
FD. 30" LAUREL S 41° E 10 <sup>6</sup>/<sub>8</sub> FT.  
TREE NOW DEAD.

BLAZE & SCRIBE 2 NEW  
TREES:  
14" FIR S 63 <sup>1</sup>/<sub>2</sub>° W 25 <sup>8</sup>/<sub>8</sub> FT. MKD.  
"AP CSBT"  
23" FIR S 87° E 31 <sup>6</sup>/<sub>8</sub> FT. MKD.  
"AP CSBT"

COR. IS 1 FT. NORTH OF NEW  
E. & W. FENCE.

FEB. 20, 1961

C.S. File No. J.B. 192/99-35  
\* Milo E. Godfrey C.P.