

RENEW AP (335'15" W 5.39 CH. FROM
V.P. FOR NORTH $\frac{1}{4}$ COR. S5 T28S R7W)
FOUND - BRASS CAP AT COR. NO
TRACE OF SW BT FOUND NW $\frac{1}{4}$
NE BT STUMPS ONLY. SE BT
IN GOOD CONDITION

NEW BT

9" R. FIR BEARS N29 $\frac{1}{2}$ ° E 26.2
SCRIBED AP CS BT

RESCRIBE ORIG. NOW 32" LAUREL
BEARS S42° E 29.3'

★

✓

RENEW NW COR. SEC. 5 T28S R7W

FOUND - BRASS CAP AT COR. $\frac{1}{4}$
BOTH B.T.S. SE BT NOW SNAG
ONLY SHOWS GOOD SCRIBING "W
SW BT " NOW 30 S41° E 33.8"

NEW BT
24" W FIR BEARS S49° E 45.0
SCRIBED NW $\frac{1}{4}$ COR. BT

✓ FEB - 20 - 1961

VA R 20 $\frac{1}{2}$ ° J.B.
M.B.
C.P.

★

✓

C.S. File No. 49/79-34