

RENEW $\frac{26}{35}$ / $\frac{25}{36}$ T24S R8W

FOUND - ORIG 18" NOW 32" K FIR
S 80° E 27.7' I OPEN & FIND GOOD
SCRIBING "8". I FIND ORIG 18" NOW
32" R. FIR N 85° E 39.3' SHOWS GOOD
SCARS I DO NOT OPEN ALSO I FIND
ROTTED BASE OF LARGE FIR THAT
CHECKS BEARING & DIST. FOR ORIG SW BT
NO TRACE OF ORIG 6" CHINQUAPIN FD.

SET BRASS CAP AT COR MIND.

$\frac{526}{535}$ / $\frac{525}{536}$ T 24S R8W COUNTY
SURVEYORS OFFICE 1958

NEW B.T.S

10" HEMLOCK BEARS N 72° W 27'
SCRIBED S 26 T 24S R8W CS BT.

7" W. FIR BEARS S 51° E 18'
SCRIBED S 36 T 24S R8W CS BT.

4" R. FIR BEARS WEST 196'
SCRIBED S 35 CS BT

16" CEDAR BEARS N 70° E 42'
SCRIBED S 25 T 24S R8W CS BT
BCU

5/1958

GOVERNMENT VITALS
CS 49184-3