

Renew Sec. Cor.

RBN

35 | 36 T245

2 | 1 T255

Found:

30" Cedar (Now snag)
N38W 24.9' full scribbling Vis.

11" R Fir N65 1/2 E 53.3
Scribbling Visible
Other trees Down

Brass Cap (CS 1958)
at Corner *Rev. #7*

New Bearing Trees:

7" D. Fir N63W 22.3
Marked T245 RBN S35
CS BT

5" W Fir S35W 20.3
Marked T255 RBN S2
CS BT

8" D Fir S77E 10.5'
Marked T255 RBN S1
CS BT

April 15, 1965

BR
MS

#258
#29

+X✓