

Section 35 Twp 24S. Rge B W

Date: 11-23-65


Not Renewable

How was corner identified? FROM SUSPECTED B.T.

FROM SUSPECTED B.T.

Condition of corner: NO MONUMENT.

NO MONUMENT.



COUNTY SURVEY
APR 5 1965
 Best route to reach corner: LITTLE WOLF CREEK RD.

Quadrant	NE	SE	SW
Species & Size	FROM TAGS →	D.F. 1/2 572	
Dist. & Bearing		?	
Condition of Scribe		?	
Original or Resurvey			
Appearance of B.T.		<u>BLU DOWN</u>	
Tags, Marks, etc.		<u>ROSE ANGLE COR. TAG</u>	<u>0</u>

Other Remarks:

We were unable to

determine exact

location of BT as it

is down & out of place

we find no rock or other

BT. BENCHT - 21M

Signed

BRP

(N. Found)