

RENEW $5 \frac{1}{4}$ 530 T 305 R 2 W

FOUND - MOUND OF ROCK AND BT'S AS RECORDED BY B.B.T. 1920 THE NE BT SHOULD BE 60" FIR RECORDED 10" FIR. BOTH BT'S ALIVE & IN GOOD CONDITION & BOTH SHOW GOOD SCRIBING.

SET BRASS CAP IN MOUND OF ROCK MARKED $5 \frac{1}{4}$ 530 T 305 R 2 W

COUNTY SURVEYORS OFFICE 1958

SCRIBED NEW BT IN NE

14" W FIR BEARS N 27° E 49.5' SCRIBED $1 \frac{1}{4}$ 530 CS BT

MAY 7-58

NOTE - THE N $1 \frac{1}{4}$ COR SEC 31 HAS GOOD ROCK (WITH T ON TOP & 4 ON S. SIDE) ALSO BOTH BT'S OK.

T 305 R 3 W

RENEW COR. 525 | 530
 536

FOUND - BT AS RECORDED BY BOYER 1939, 16" NOW 24" FIR N 27° W 230' I ALSO FD. OF 16" 11" NOW 20" CEDAR N 67° 34' E 178'. BOTH BT'S HAVE GOOD SCRIBING AND ARE ALIVE & IN GOOD CONDITION.

SET BRASS CAP MKD COUNTY SURVEYORS OFFICE 1958

525 | 530 T 305
 536

R 3 W R 2 W

NEW BT.

12" R FIR BEARS N 33° E 145' 530 T 305 R 2 W COR BT. MARK SCRIBED

NOTE - I FLD CLOSING COR FOR

536 | 530 AS RECORDED BY
 531 BOYER 1939 - PIPE & BT'S OK.