

RENEW NORTH 1/4 COR. 5 18 T 30 S R 2 W

FOUND - ORIG. 18" NOW 26" FIR STUMP
S 21° E 257' SHOWS GOOD SCRIBING S 18°
ORIG. 5" NOW DOWN 8" HEMLOCK SHOWS
GOOD SCRIBING S 18° BT" S 21° E 396'
I ALSO FIND 1" I.P. 3' ABOVE GR.
AT COR.

I SET 3/4" I.P. ALONGSIDE I.P.

NEW BTS.

17" R. FIR BEARS S 62° W 77.5'
SCRIBED 1/4 S 18° BT.

24" SUGAR PINE BEARS N 50° W 35'
SCRIBED 1/4 S 18° BT.

JAN 30 - 58
VAR 20 1/2° J.B.
M.G.
S.B.



RENEW SOUTH 1/4 COR. 5 7 T 30 S R 2 W

FOUND - ORIG. 42" NOW 40' TOP DEAD
R. FIR COR. TREE SCRIBED 1/4 S 7
ON NORTH FACE. I ALSO FIND BOTH
ORIG. BTS NOW SCRIBED STUMPS.

SET WIT COR. 5' EAST OF 1/4 COR.
MAD. WIT. COR. 5' WEST TO SOUTH
1/4 S 7 T 30 S R 2 W COUNTY
SURVEYORS OFFICE 1958

NEW BTS.

8" R. FIR BEARS N 3° W 23.7'
SCRIBED W.C. 1/4 S 7 CS BT

6" R. FIR BEARS N 47° E 290'
SCRIBED W.C. 1/4 S 7 CS BT



DIETZEN NO. 385-6