

Renew Sec. COR. $\frac{154}{59}$ T255 R8W

Fd. O.B.T.s as follows —

Orig. 30" Now 47" Fir N. $66\frac{1}{2}^{\circ}$ E. 132 $\frac{1}{2}$ ft.

2 live - shows good scar - don't open

This B.T. on N. side of creek course E.

Orig. 45" Now 62" Fir S. $79\frac{1}{2}^{\circ}$ E. 60 $\frac{1}{2}$ ft.

2 live - we open & find "59" scribe.

Set 1" I.P. & Brass cap MKD. "COUNTY

SURVEYORS OFFICE 1967 T255

$\frac{154}{59}$ R8W " & MK. New B.T.s —

7" Hemlock N. 81° E. 52 $\frac{1}{2}$ ft.

MKD. "T255 R8W 54 CS BT"

7" Hemlock S. 48° E. 49 $\frac{1}{2}$ ft.

MKD. "T255 R8W 59 CS BT"

This COR. Lies Steep N.E.

Slope approx. 90 ft. S. of creek

4 ft. wide course E.

also 256" Fir N. 41 $\frac{1}{2}$ Now 66 $\frac{1}{2}$ ft.

2 live - shows good scar - don't open

UNRECORDED. —

Sept 15, 1967

Chet Sorensen
of B.L.M.

U.R.T.
J.H.
D.W.

O.N. J.W.B.

C.S. File No. 42/88-14