

REN. T20 SR6 5 & 6 W 25/30

FD ORIG. 9" FIR (NOW 35" DIAM.) 36/31

N 58° E 20⁵/₈ FT. CUT OPEN & FD.
GOOD SCRIBING "S". TREE IN VERY
GOOD CONDITION.

FD. BURNED REMAINS OF OLD FIR
SNAG N 3° W 42⁹/₈ FT. NO SCARS OR
SCRIBING FD.

FD. FIR TREE (NOW 40" DIAM.)
S 17° E 5³/₈ FT. UPROOTED & DOWN.
SHOWS GOOD SCAR.

ROTTED REMNANTS OF S.W. B.T.
FD. GOOD REVERSE SCRIBING VISIBLE.
IMPOSSIBLE TO DETERMINE WHERE
TREE HAD STOOD.

71) AT COR. SET IRON PIPE WITH BRASS
CAP MKD. 'DOUG. CO. SURVEYOR'S OFFICE

1962 T20 S R 525/530 R "
W 536/531 W

BLAZE & SCRIBE 3 NEW TREES:

17" DOUGLAS FIR N 50° W 37⁸/₈ FT.

MKD. "T20 SR6 W S 25 DC5 BT"

8" INCENSE CEDAR S 56¹/₂° W 11¹/₄ FT.

MKD. "T20 SR6 W S 36 D 15 BT"

40" DOUGLAS FIR S 18¹/₄° E 48³/₈ FT.

MKD. "T20 SR5 W 531 D 15 BT"

C.S. File No. 49/89

+ * P. Milo E. Coffey

JAN. 11, 1962
M.G.-V.T.-C.P.