

RENEW 2615
35136

FOUND - 1/2" I.P. AT CAR ORIG
18" NOW 18" FIR BEARS S 40° E 13.2'
STAMPS GOOD SCRIBING 536 OR
8" NOW 14" DOWN FIR 58' W
33.0" NOT 29.6' NO TRACE OF
ORIG NW ENE BT FOUND W/E
OPENED SW BT FOUND GOOD
SCRIBING

SET BRASS CAN ALONGSIDE
1/2" PIPE AND MARKED COUNTY
SURVEYORS OFFICE 1961 521525
T 20 S R 6 W
535 536

NEW BT
16" R. FIR BEARS S 21° E 54.0'
SCRIBED 536 T 20 S R 6 W C 5 BT

5" R. FIR BEARS S 79° W 28.3'
SCRIBED 535 C 5 BT

22" R. FIR BEARS N 48° W 29.6'
SCRIBED 526 T 20 S R 6 W C 5 BT

NO TREES NEAR TO N E

U.C. Z. H. 616
G. H.
D. A.

DIETZEN NO. 38518

C.S. FR...