

REN. T 20 S R 6 W $\frac{1}{4}$ S 19
S 30

FD. FIR TREE (NOW 30" DIAM.)
N 28° W 8 6 FT. TREE HAS BEEN
CHOPPED OPEN PREVIOUSLY. GOOD SCRIBING
"4" VISIBLE ON OLD FACE, TREE IS
LEANING BADLY. NOT UPROOTED YET, BUT
MAY NOT STAND LONG.

FD. BADLY DECAYED FIR SNAG S 30° W
2 6 FT. FRAGMENTARY BUT UNMISTAK-
ABLE SCRIBE MARKS VISIBLE ON OLD
FACE.

AT COR. SET IRON PIPE WITH BRASS
CAP MKD. "DOUG. CO. SURVEYOR'S OFFICE
1962 T 20 S R 6 W $\frac{1}{4}$ S 19
S 30

BLAZE & SCRIBE NEW TREES:

7" DOUGLAS FIR N 33° W 129 7 FT.
MKD. " $\frac{1}{4}$ S 19 DCS BT "

9" DOUGLAS FIR S 25° E 52 6 FT.
MKD. " $\frac{1}{4}$ S 30 DCS BT "

FEB. 6, 1962
M.G.
V.T.
C.P.
Wm. E. Godfrey

+ * ✓

C.S. No. 49/89-18