

REN. T20SR6W

28/27

FD. 1/2" ROD (REINFORCING ROD)

33/34

SET BY HAYDON IN 1950.

FD. OLD FIR SNAG - OUTSIDE ROTTED AWAY S72°W 13 1/2 FT.

FD. FIR SNAG (NOW 30" DIAM.) S76°E 13 1/2 FT. HAYDON'S SCRIBING "BT" VISIBLE IN PARTIALLY HEALED SCAR.

FD. FIR TREE (NOW 10" DIAM.) SOUTH 17 1/2 FT. (HAYDON & RAINES' BT) SCRIBING VISIBLE IN PARTIALLY HEALED SCAR "BT."

1 RESCRIBE "T20SR6W S34 CS" ABOVE OLD AT COR., ALONGSIDE 1/2" ROD, SET IRON

PIPE WITH BRASS CAP MAB "COUNTY SURVEYOR'S OFFICE 1962 T20SR6W S28/27" 333/334

BLAZE & SCRIBE 2 NEW TREES:

28" FIR TREE S 77° W 26 1/2 FT. MKD. "T20SR6W S33 CS BT."

22" FIR TREE N 3° E 63 3/4 FT. MKD. "T20SR6W S27 CS BT" (ONE BLAZE)

(NO TRACE OF ANY OTHER ORIG. OR RENEWAL B.T.'S, ETC.) NO OTHER TREES NEAR.

JAN. 15, 1962

Paul E. Coffey

M.G.
V.T.
C.S. No. 28/27

C.S. File No.

+ * O ✓