

REN.

T 21 S R 5 W

11/12

FD. ROTTED FIR STUMP N 67° W

14/73

45² FT. SCRIBING VISIBLE ON OLD FACE "T 21 S R 5 W"

FD. BADLY BURNED FIR SNAQ N 62° E

33⁰ FT. NO SCRIBING FD.

FD. FIR TREE (NOW 60" DIAM.)

S 18° E 54⁸ FT. OLD INJURY ON BARK.

NO SCRIBING FD.

FD. FIR STUMP (NORTH FACE BURNED AWAY)

S 10° W 91¹ FT. NO SCRIBING FD.

AT COR. SET IRON PIPE WITH BRASS

CAP MKD. "COUNTY SURVEYOR'S OFFICE

1962 T 21 S R 5 W. S 11 | S 12 "

S 14 | S 13

BLAZE & RESCRIBE 60" FIR S 18° E 57² FT. (TO CENTER) "T 21 S R 5 W S 13 CS BT"

BLAZE & SCRIBE 3 NEW TREES:

18" DOUGLAS FIR N 48° E 37³ FT. MKD.

"T 21 S R 5 W S 12 CS BT"

6" DOUG. FIR N 45° W 27⁰ FT.

MKD. "T 21 S R 5 W S 11 CS BT"

18" DOUGLAS FIR S 5° W 58² FT.

MKD. "T 21 S R 5 W S 14 CS BT"

FENCE COR. - FENCES EAST & NORTH -

BEARS EAST 24 FT.

JAN. 9, 1962

M.G. - V.T. - C.P.

+ * O V Mills E. Sperry

C.S. File No. 29/100