

REM.

T 21 S R 5 W

1/4 S 1/2 S

FD. PARTLY ROTTED FIR STUMP
 (NOW 30" DIAM.) N 78° E 20 1/2 FT.
 CHOPPED OPEN & FD. GOOD SCRIBING
 "BT" THIS STUMP HAD BEEN RESCRIBED
 "1/4 S" SHORTLY BEFORE IT WAS CUT.

FD. FRAGMENTS OF ROTTED FIR
 STUMP (IN PLACE) S 23° W 22 1/2 FT.
 PORTIONS OF SCRIBING VISIBLE ON
 SMALL SLIVER.

AT COR. SET IRON PIPE WITH
 BRASS CAP MKD. "COUNTY SURVEYOR'S
 OFFICE 1962 T 21 S R 5 W 1/4 S 1/2 S"

BLAZE & SCRIBE NEW TREES:

7" DOUG. FIR N 33° E 6 3/4 FT.

MKD. "1/4 S 1 CS BT"

19" HEMLOCK S 75° W 26 8/10 FT.

MKD. "1/4 S 2 CS BT"

APR. 30, 1962

M.G.

V.T.

Milo E. Goffroy

T * V C

G. S. File No.

49/89-58