

REN

T 21 S R 5 W

$\frac{1}{4}$  S  $\frac{1}{2}$  S  
28 1/2

FD.  $1\frac{1}{4}$ " IRON PIPE IN FENCE  
LINE (APPROX. N. & S.)

FD. 16" INCENSE CEDAR MKD.  
BY GARDINER IN 1955.  $S 6^{\circ} E$   
 $92^{\circ}$  FT. MKD. " $\frac{1}{4}$  SBT" - SCAR NOT  
CLOSED.

FD. CEDAR STUMP 6 FT. HIGH.

N  $55^{\circ} W$   $81\frac{1}{2}$  FT. - 2" X 6" BOARD  
NAILED TO STUMP SCRIBED " $\frac{1}{4}$  SBT"

1 BLAZE & SCRIBE ONE NEW  
TREE;

8" WHITE FIR  $S 14^{\circ} W$   $92\frac{1}{2}$  FT.  
MKD. " $\frac{1}{4}$  S 28 CS BT"

FENCE COR. ON S. SIDE SAND  
CREEK ROAD BEARS  $N 6^{\circ} E$   $62^{\circ}$  FT.

DID NOT SET BRASS CAP.

MAY 11, 1962

M.G.

V.T.

C.P.

*W. E. Godfrey*

+\*✓ ○

G. S. File No. 49/89-59