

4

130.3 ✓

N65°00'W ✓

126° ✓  
145

N65°W

3

72°41'  
36'20" L

28°30'  
57.2

331.1 ✓

578°39'W ✓

578½W

120°35'  
300°

2

22°58'  
11°29' L

487.1 ✓

N89°52'W ✓

31°32'  
253.1

WEST

125°15'  
300°

1

1°44'  
0°52' L

325.9 ✓

N89°00'W N89°W

120°15'  
35.25

120°20'  
300°

M.C.

FR BRASS CAP RECOVERED BY C. SURNEYA

52

NEST SHORE 1957.

T 23 S R 10 W

M/C SEC'S 11/12

FOUND LAUREL TREE, NOW 20"

GROWING OUT OF OLD LAUREL STUMP

FOUND DEAD FIR SNAG, NOW 33"

DIAM., BARK SCRIBING "S 12 B"  
12

APPEARS ABOUT 20 YRS OLD. OLD

SCAR BELOW BARK SCRIBING FACING  
CORNER. - N 20° E 15.2 FT. FROM LAUREL

TREE TO NW (N 30° W 11.9 FT)

UPROOTED AND DOWN - NEARLY ALL IN

LAKE. FOUND "S" BARK SCRIBED ON IT.

FOUND 36" FIR N 40° W 17 7/8 FT.

WITH BARK SCRIBING "M C S 12

T 23 S R 10 W BT" PLAINLY VISIBLE.

THIS SCRIBING APPEARS ABOUT 20 YRS.  
OLD.

BLAZE & SCRIBE LAUREL TREE

"M C S 11/12" FOR CORNER

RE SCRIBE FIR SNAG TO NE.

"M C S 12 CS BT" IN BARK BELOW

OLD SCAR. NO LIVE TREES NEAR

TO EAST OF MEANDER COR.

FEB. 5, 1958

C. S. File No. 49/90

T 23 S R 10 W

M/C SECS T11 12

FOUND FIR TREE, NOW 32" DIAM.  
S 19° W 39.0 FT. THIS TREE HAS  
BEEN CHOPPED OPEN EXPOSING FACE  
AND SCRIBE MARKS "S 11 T 23 R 10"  
RING COUNT SHOWS THIS TREE TO HAVE  
BEEN SCRIBED APPROX. 20 YRS. AGO.

FOUND FIR TREE, NOW 16" DIAM  
N 78° E 28.5 FT. SHOWING GOOD SCAR.  
DID NOT CHOP THIS TREE OPEN.

THIS CORNER FALLS IN ROAD FILL  
IN SLIDE AREA

AT COR. SET. FIR POST 4" X 4" X 10'  
SCRIBED "M C S 11" ON WEST SIDE  
"M C S 12" ON EAST SIDE AND  
"C S" ON SOUTH SIDE.

FEB. 5, 1958

✓ C. S. File No. 49/90

RENEW  $\frac{1}{4}$  COR.  $\frac{11}{14}$  T235 R10W

FOUND - BOTH B.T.S. SCRIBED

1906 RESURVEY. I OPEN N.W.

BT & FIND GOOD SCRIBING BT

THE SW BT SHOWS GOOD SCAR I

DO NOT OPEN. BOTH NOW 13'. I

ALSO FIND BOTTOM SECTION OF

ORIG. COR. STAKE UNDER SURFACE.

SET BRASS CAP AT COR. MKD.

COUNTY SURVEYORS 1958

$\frac{1}{4}$   $\frac{511}{314}$  T235 R10W

NEW BT 1" R.F.R BEARS

NORTH 19.8 SCRIBED  $\frac{1}{4}$  S 11 CS BT.

$\frac{1}{4}$  COR  $\frac{11}{14}$   
T235 R10W

22.5 ✓

581° 21' W ✓

40° 05' ✓  
29.4

43

83° 40' R

260.0 ✓

53° 41' W ✓

+ 17° 45' ✓  
83.5

42

20° 42' ✓  
10° 21' R

+ 4° 15' ✓  
181.0

56° 40' E ✓

JAN 23 1958  
M. G. D. T. W.  
D. B. L. S. W.

RENEW M.C. 11/12 PUS SHORE  
LOOK LAKE

FOUND - 40" NOW 4-4" FIR  
S 48° W 75' SHOWS GOOD SCAR I DO  
NOT OPEN. FIND NOW 2-4" ALDER  
N 37° E 6.7' GOOD BARK SCRIBING  
COR 1 12 T 233 R 10 W  
SET BRASS CAP AT COR NWD. M.C.

T 23 S R 10 W COUNTY SURVEYORS  
511 1012 OFFICE 1958

NEW BT 13" CEDAR BEARS 32.2'  
SAME SCRIBED MC 512 CS BT  
NOTE - I ALSO FIND 4" X 4" SCRIBED  
STAKE AT CORNER VERTICAL BUT  
COVERED WITH SOIL.

DIETZEN NO. 388-6

75' ✓

55' ✓

54' 25' ✓

NOTICE  
LINE REASON  
SEE  
PAGE 13

7/15  
16/15

51

0°37'  
8°19'

580°W 2509  
+1307'

50

157°13'  
29°37'

N 15°W - 227°W  
2118'

19-000  
11/12

RENEW 1/4 COR. 11/12 T235 R10W  
FO 4" X 4" STAKE AT COR. AND ORIG.  
FIR NOW 39"

HAS OPEN FACE SUMMIT SCISSORS  
VISIBLE, I BARK SCRIBE THIS BT.

SET BRASS CAP AT CORNER MARKED  
1/4 S 11/5 12 T235 R10W

NEW BT. 10" HEMLOCK BEARS

5 1/2° E 19.7 SCRIBED 1/4 S 12 CS BT

10"

✓

RENEW NORTH 1/4 COR. SECTION 120S

NO POSITIVE IDENTIFICATION  
ORIG. BITS. ED. JEFF. C.S. MILLER  
FOR DETERMINING POSITION OF THIS  
CORNER

SET BRASS CORNER MKD. COUNTY  
SURVEYORS OFFICE 1958  
N 1/4 S 11 T 23 S R 10 W

NEW BITS.

13" HEMLOCK BEARS S 85° W 122.3  
SCRIBED 1/4 S 11 C S BT

7" HEMLOCK BEARS S 68° E 40.7  
SCRIBED 1/4 S 11 C S BT

VAR 20°

FEB. 3 - 1958

H. B.  
M. G.

✓ ✓

DIETZEN NO. 385-6

RENEW SEC. CAR  $\frac{312}{1011}$  T235 R10W

FOUND - ORIG. 9" NOW 14" FIR

N 25° W 18.5' I OPEN & FIND GOOD

SCRIBING 1 3" I ALSO FIND 30" FIR

THAT CHECKS BEARING & DIST. FOR ORIG.

S.W. BT.

SET BRASS CAP MND COUNTY

SURVEYORS OFFICE 1958. 53 | 52

T235 R10W

510 | 511

NEW BT.

10" R. FIR N 49° E 16.5

SCRIBED 52 T235 R10W CS BT.

10" R. FIR N 80° W 16.8'

SCRIBED 53 T235 R10W CS BT

30" E. FIR S 50° W 14.3'

SCRIBED 510 T235 R10W CS BT

11" MYRTLE S 58½° E 40.9'

SCRIBED 511 T235 R10W CS BT.

✓ FEB. 3 - 58

J. B.

M. G.

S. B.

RENEW W 1/4 COR. 511

FOUND - ORIG. 20" NEW 36" FIR  
507 1/4 VV RECORDED 79.9' H HED  
SHOULD BE 80.9' H HED  
GOOD REPAIRING 1/2" WITH 1/4" H HED  
BT ALSO USED AS BT FOR 1/4 COR  
1/4 COR. ALSO H HED CLUMID OF 1/4 COR  
H HED CHECKS BEARING & DIST TO  
RECORD MADE ONLY A DOWN ALDER  
HAS SMALL SECTION OF 1/4 COR  
OLD FACE TO DESCRIBING VISIBL. C. P.

NOTE - BEARING & DIST BETWEEN  
1/4 COR. CHECK RECORD.

SET BRASS CAP AT COR. 1/4 COR.  
W 1/4 S 1/4 T 23 S P 10 VV  
COUNTY SURVEYORS OFFICE 1952

DIETZGEN NO. 385-6

NEW BTs

28" R. FIR 3250 FT 1230  
SCRIBED W 1/4 S 1/4 COR BT

35" R. FIR 4150 FT 62.9  
SCRIBED W 1/4 S 1/4 COR BT

VAR 20 FT.

FILED 1952  
L. B. V. P.  
A. B. O. P.  
L. O. V. P.

✓✓

RENEW  $\frac{1}{4}$  COR SEC. 10 T 23S

R10W

FOUND - BOTH ORIG. BTS.  $\frac{1}{4}$

BOTTOM SECTION OF WOOD STAKE

AT CORNER. ALSO CHECK BEARING

$\frac{1}{4}$  DIST TO LARGE ROTTED SNAG

RECORDED AS LIVE TREE 38'

NORTH OF COR. I DO NOT OPEN EITHER

BT SHOW GOOD SCARS. THE NE BT

NOW 40" FIR. THE SW BT NOW 56"

FIR. THIS BT SAME TREE USED FOR

$\frac{1}{4}$  COR SEC. 10

NEW BTS:

20" R. FIR BEARS N 11° W 46 1/2'

SCRIBED  $\frac{1}{4}$ S 10 CS BT

18" R. FIR BEARS S 82 1/2° W 41.8'

SCRIBED  $\frac{1}{4}$ S 10 CS BT.

SET BRASS CAP MKD  $\frac{1}{4}$ S

10 T 23S R10W COUNTY SURVEYORS

OFFICE 1957.

✓✓ J. BYRON

M.G.

J.B.

9045 - 90906

54

MARCH 18-58

272.55

99700

(90°F)

898

J. BYRON

M. G.

S. B.

+19°55'  
1089

N 90° 14' E  
79.3'

90° 20'

SP 9° 28' 20" E  
178.8'

87° 42'

81° 42'

82.27'

159.43'

3552'

184-256 W

1400  
1400  
1400

DIETZEN NO. 385-6

29  
30  
N 5° 14' W

S 50° 35' W

157.60'

184.57'

BT

16" R. FIR BEARS N 73° W  
143.3' Scribed

5/8" SILENT  
BEARING DISTANT  
TO CHISELED ON TOP

5' X 5' X 7' ROCK  
WITH B.O. CHISELED ON  
SOUTH FACE NEAR TOP

OST 2' ID  
6' UNDER  
FOR INIT. PT. W  
SOUTH FACE

C. S. File No. 49/90  
N 5° W 20°

CS FILE FOLDER

CONTAINS

MORE

INFORMATION