

RENEW $\frac{1}{4}$ COR. 11 | 12 T295 R9 W

FOUND - ORIG. 9" NOW 30" W. FIR

N78°E 7.9' I OPEN NEAR BASE

$\frac{1}{4}$ FIND GOOD SCRIBING BT. I ALSO

FIND ORIG. 15" NOW 30" FIR, DOWN $\frac{1}{4}$

PARTLY ROTTED CHECKS BEARING

$\frac{1}{4}$ DIST S77°W 238'

SET BRASS CAP AT CORNER MXD.

$\frac{1}{4}$ 511 | 512 T295 R9 W

COUNTY SURVEYORS OFFICE 1958.

NEW BTS.

12" W. FIR BEARS S 64° W 18.7'

SCRIBED $\frac{1}{4}$ 511 CS BT

12" W. FIR BEARS S 40° E 34.1'

SCRIBED $\frac{1}{4}$ 512 CS BT

SEPT. 26 - 58

J. B.

VAR 20 $\frac{1}{2}$ '

M. G.

S. B.

✓
CS 49 / 100 -24