

RENEW  $\frac{43}{9/10}$  T 29S R8W

FOUND - ORIG. 30" N.W. 36" FIR STUMP  
N 70° W 8.6' SHOWS GOOD BARK SCRIBING  
"T 29S R8W" ORIG 30' N.W. 40" FIR  
S 60° W 15.8' SHOWS GOOD BARK SCRIBING  
"T 29S R8W S BT" THE BT HAS BEEN  
DE BARK SCRIBED 10 YEARS AGO. IT  
FIND NO TRACE OF SECTION BT.

SET BRASS CAP AT CORNER MKD  
 $\frac{64}{53}$  T 29S R8W COUNTY SURVEYORS  
 $\frac{59}{510}$  OFFICE 1958.

NOTE - I FIND  $\frac{3}{2}$ " IRON ROD BEARS N 80° E  
12 FT.

NEW BTS -  
7" W. FIR BEARS S 7 $\frac{1}{2}$ ° E 22 $\frac{1}{2}$  FT.  
SCRIBED S 10 T 29S R8W CS BT

11" W. FIR BEARS N 61° E 41 $\frac{1}{2}$  FT.  
SCRIBED S 3 T 29S R8W CS BT

24" DOUG. FIR BEARS N 87 $\frac{1}{2}$ ° W  
80 FT. BARK SCRIBE "T 29S R8W S 9 CS"  
SCRIBE "BT" IN WOOD

FILED  
RECEIVED

SEP 24 1958

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

✓

U. S. File No. 49/100-27

DIETZEN NO. 385-6