

RENEWY $\frac{1}{4}$ COR. 9/18 T29S R8W

FOUND — ORIG. 10" NOW 26" FIR
DOWN OPEN FACE SHOWS GOOD SCRIBING
532' W R. 6' I ALSO FIND 1" I.R. AT COR.
40' FIR NOW DEAD SHOWS GOOD BARK
SCRIBING $\frac{1}{4}$ S S BT. THIS BT. I.R.
SET BY 4 BOYER 1929 I FIND STUMP
HOLE THAT CHECKS BEARING & DIST.
FOR BOYER'S 5 W BT.

I DO NOT SET BRASS CAP AT COR.

NEW BT'S

9" W. FIR BEARS 542' W FF. 3
SCRIBED $\frac{1}{4}$ S S BT

14" CEDAR BEARS 525⁰' E 88.4'
SCRIBED $\frac{1}{4}$ S S BT

NOTE — CEDAR SCRIBED 5'
ABOVE GROUND

DIETZGEN NO. 3885-6

FILED

RECEIVED

SEP 25 1958

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

C. S. File No. 49/100-351