

RENEW  $\frac{1}{4}$  COR. 23/24 T29S R8W

FOUND - ORIG 20" N.W. 34" CEDAR  
S 10° E. 11.9' PREVIOUSLY OPENED SHOWS  
PARTS OF GOOD SCRIBING ON PARTLY  
ROTTED FACE "4". I FIND NO TRACE  
OF ORIG. SW BT, WHICH WOULD BE IN CRK.

SET BRASS CAP AT CORNER MKD,

$\frac{1}{4}$  S 23/S24 T29S R8W COUNTY  
SURVEYORS OFFICE 1958.

NEW PTS.

I DESCRIBE 34" CEDAR S 10° E 12.7'

$\frac{1}{4}$  S 24 CS BT

32' R. FIR BEARS S 55° W 30.2'

✓✓

FILED

RECEIVED

OCT 14 1958

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

CS 49/100 H