

RENEW  $\frac{1}{4}$  COR 1532 | 533 T 295 R 8 W  
FOUND - BOTH B.T.S AS FILED BY  
BOYER, I DO NOT FIND EITHER ORIG.  
B.T.S. BOYERS 40" CEDAR N 55 $\frac{1}{2}$ ° E  
23.0' GOOD CONDITION SCRIBING -  
VISIBLE, 36" NOW DOWN FIR  
S 48° W 148' SHOWS GOOD BARK  
SCRIBING. I ALSO FIND SCRIBED  
STAKE AT CORNER.

I SET BRASS CAP ALONG -  
SIDE STAKE & MARK.

$\frac{1}{4}$  532 | 533 T 295 R 8 W  
COUNTY SURVEYORS OFFICE  
1958.

NEW BT.

7" W. FIR BEARS S 79° W 172'  
SCRIBED  $\frac{1}{4}$  532 CS BT

VAR 20 $\frac{1}{2}$ '

OCT 30 - 58

J.B.

M.G.

S.B.

\*

CS 49/100-44