

27 28
RENEW 325' T295 R9W

FD ORIG. 28" Now 32" FIR STUMP
N 14° W 277' PREVIOUSLY OPENED
NEAR BASE SHOWS GOOD SCRIBING
'BT' ORIG. 28" Now 32" FIR STUMP
S 55° W 106' I OPEN & FIND
GOOD SCRIBING 'BT' NO TRACE
OF SE OR SW BT FD

SET CROSS CAP AT CORNER
MND COUNTY SURVEYORS OFFICE
1959 527 | 526 T295 R9W
534 | 535

NEW BTS.

10" W. FIR BEARS N 80° W 459'
SCRIBED S 22 T295 R9W CSBT

7" W. FIR BEARS S 53° W 238'
SCRIBED S 34 T295 R9W CSBT

14" MAPLE BEARS S 55° E 295'
SCRIBED S 35 CSBT

10" FIR BEARS N 62½° E 885'
SCRIBED S 26

NO FENCE IS
EAST OF COR

* T. B. OCT 13 1959
M. G. ✓ C. S. File No. 49/100-170