

REN.

T22SR9W

C.C. 25
SELS 36

(ON W. LINE T22SR9W)

FD. FIR TREE (NOW 52" DIAM.)

S68°E 44² FT. - CHOPPED OPEN
+ FD. GOOD REVERSE SCRIBING.

FD. FIR TREE (NOW 28" DIAM.)

S25°W 40² FT. - SHOWS GOOD AXE
SCAR. - RESCRIBE "T22SR9W S36CSBT"

FD. FIR TREE (NOW 48" DIAM.)

N67°W 43⁶ FT. - SHOWS GOOD AXE
SCAR. - INJURY ON N.W. FACE SHOWS
TREE ROTTING IN CENTER.

(ALL DISTANCES ON D.B.T.'S ARE
SLOPE DISTANCES FROM CENTER OF TRUNK.)

AT COR. SET IRON PIPE WITH
BRASS CAP MKD. "COUNTY SURVEYOR'S
OFFICE 1963 T 22SR9W CC S25^R
S36^W

BLAZE & SCRIBE 2 NEW TREES:

11" DOUG. FIR N 66° E 22³ FT.

MKD. "CC S25 S36 CSBT"

8" DOUG. FIR N 38° W 16² FT.

MKD. "T22SR9W S25 CSBT"

- COR. LIES NEARLY AT FOOT OF
STEEP SOUTH SLOPE, IN UPPER EDGE
OF CUT BANK ON OLD LOGGING ROAD.

JAN. 18, 1963

M.G.

V.T.

M.S.

Milo E. [Signature]

C.S. File No. 42103-9

()
+ * ✓