

41. 5722 E

RENEW $\frac{1}{4}$ COR 26 | 25 T 303 RPW

FOUND - STEEL FENCE POST AT COR # BOTH ORIG. BTS.

ORIG 36" NOW 48" FIR S 23° E 211'

SHOWS FAINT SCRIBE MARKS " $\frac{1}{4}$ " S"

(BARK SCRIBED)

ORIG 30" NOW 42" FIR S 67° W 119'

SHOWS FAINT SCRIBE MARKS " $\frac{1}{4}$ " S"

(BARK SCRIBED)

IT DO NOT GET BRASS CAP AT COR.

NEW BTS.

8" R. FIR BEARS S 72 $\frac{1}{2}$ ° E 450'

SCRIBED " $\frac{1}{4}$ " S 2 $\frac{1}{2}$ COR

IT RE-SCRIBE (BARK) 42" R. FIR

S 67° W 13.5' $\frac{1}{4}$ S 26 COR

✓

RENEWED $\frac{2}{4}$ COR 26 | 25 T 303 RPW

THIS COR. AS RECORDED BY ROGER GEE 1955 EXCEPT A STEEL FENCE POST HAS BEEN PLACED AT CORNER.

PUT NOTATION ON GEE'S CORNER ✓

AUG. 14-58

J.B.
M.G.
S.B.

FILED

RECEIVED

AUG 14 1958

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

C. S. File No. 79/100-2

DIETZSEN NO. 385-B